



REPORT OF THE OCCURRENCE OF OPERATIONAL ACCIDENTS, SPILL OF POLLUTANT SUBSTANCES, SICKNESS OR INJURY

1-	Name of the vessel: WG COOK
2-	Date and time of the first observation: 12.02.2012 AT 11:52 AM (local).
3 -	Estimated date and time of occurrence of the event (whether an accident, a spill of pollutant substances, a sickness or injuries): 12.02.2012 AT 11:47 AM
4 -	Position of the ship when the accident or spill of pollutant substances occurred: 24°54'32.4" S / 44°06'26.1" W
5 -	Existence of deaths or injured and extensiveness of damages of the ship or machinery, and present situation: N/A
6-	Type and quantity of spilled contaminant: Isopar M. Approximately 30L.
7 -	Physical description of the event (whether an accident, a spill of pollutant substances, a sickness or injuries), informing circumstances under which the accident/spill of pollutant substances occurred, and the nature of the spill: Seismic cable parted 3Km



8-	Description of the equipment or part of them, as well as structures, tubing, tools, lifting apparatus, devices, systems, compartments, materials, areas, cargo units, among other, involved whether directly or indirectly and which, in some way, contributed to its occurrence: Seismic streamer parted. Streamer recovered 2 hours after incident happened
9 -	Description of the external factors that eventually contributed to the occurrence of the event, such as meteorological conditions, system failures, equipment defects, interaction of other elements, but not only the mentioned factors: Good weather (9knots, 1.5 max pitch)
10 -	Description of the probable causes of the accident, spill of pollutant substances, sickness or injuries, Whether they be immediately related, cumulative or circumstantial: Weak cable section.
11 -	Evaluation of consequences of the event, regarding operational continuity and damage, whether to assets, environmental protection areas, or human health: Back to normal after 2 hours.
12 -	Names of the crewmembers (only if there is a risk of sinking and/or the need to make a search, salvage or rescue): N/A
13 -	Medical information required (only if the MEDEVAC is summoned): N/A
14 -	Preventive measures taken and/or any previous measures taken: Work Boat available for recovering from such an incident.
15 -	Description of the mitigating measures taken: Work Boat recovered parted cable.
16	Present situation of the oil discharge (X) Interrupted () Not interrupted () Incapable of informing
17 -	Present location of the ship: 24°58'176" S / 044°05'180" W
18 -	Currents, winds, state of the sea and approximate heading of the oil spill: CURRENT - 0,8 KNOTS; WINDS – 9 KNOTS ; 1.5 max pitch



REPORT OF THE DELIVERY OF

19 - Identification of the professional responsible for preparation of the report, including the position held at WG:

Tin Wong - ACS WG COOK - WESTER GECO / Daniel Campbell de Andrade - ENV. TECH. WG COOK - ECOHUB

20- Date and time of delivery of the report:

12.02.2012 AT 16:30 P.M.



Daniel C. de Andrade
CAS COOK

Daniel Campbell de Andrade

Odd-1
PM WG COOK