Vessel	AHTS CAMPOS CONTENDER		**0007**	NOVEMBER, 12st 2014
Report No.	CHEVRON_ DR_ 20141112		**Block**	

FRADE FIELD	0000	FRADE FIELD	0820	ARRIVAL IN AREA THE SIMULATED RECOVERY OIL
FPOS FRADE	0820	FPSO FRADE	0900	STARTED IBAMA OIL SPILL RESPONSE DRILL
FRADE FIELD	0900	FRADE FIELD	1445	FINISHED IBAMA OIL SPILL RESPONSE DRILL / UNDERWAY
FRADE FIELD	1445	FRADE FIELD	1545	ARRIVAL AREA DIVING WITH ROV
FRADE FIELD	1545	FRADE FIELD	1710	ROV IN WATER
FRADE FIELD	1710	FRADE FIELD	2100	LOST ROV
FRADE FIELD	2100	FRADE FIELD	2130	TMS IN DECK / FOLLOW ROV
FRADE FIELD	2130	FRADE FIELD	2400	ROV MONITORING IN THE BACKGROUND

Product		0001	Receive	Discharge	Used	Corr	2400	Remarks	
Diesel M³		767.4		-	12	-	755.4	*Available for Rig*	505.4
Potable Water M³		483		-	12	-	471	*Avalable for Rig*	331
Drill Water M³		352.0	-	-	-	-	352.0	*Avalaible for Rig*	152.0
Cement MT		0	-	-	-	-	0		
Barite MT		0	-	-	-	-	0		
Bentonite MT		0	-	-	-	-	0		
SBM Mud BBL		-	-	-	-	-	-		
Base Oil BBL		-	-	-	-	-	-		
WBM Mud BBL		0	-	-	-	-	0		
Brine BBL		0	-	-	-	-	0		
SBM 11.5ppg	**BBL**	0	-	-	-	-	0		
Saraline 6.4ppg	**BBL**	0	-	-	-	-	0		
SLOP - M3	**BBL**	0	-	-	-	-	0		
SBM 10.4ppg	**BBL**	0	-	-	-	-	0		
Deck in Use (%)		45	-	-	-	-	65		

Safety / Personnel Data					
Crew	15	Rigger CD	-	Near Miss	-
Passengers	4	Safety drill	-	Pre Job	32
JSA	4	Safety Mtg	-	PTW	5
Safe WISE	-	Unsafe WISE	-	Stop Work	-

Details on Safety Reports or Drills

CREW CHANGE: 19/11/2014

PORT Liq Mud Tank status @ 2400						**STBD Liq Mud Tank staus @ 2400**				
01	0	Clean	Pad Mud	Clean		01	0	Clear	Pad Mud	Clean
02	0	Clean	Pad Mud	Clean		02	0	Clear	Pad Mud	Clean
03ET	**0**	Other	Etanol (m3)	Used		03	**32.9m3**	Clear	Slop	Used
074B1	0	Brine	TQ 01 BB	Clean		4B1	0	Base Oil	TQ 01 BE	Clean
5B1	0	Brine	TQ 02 BB	Clean		5BO	0	Base Oil	TQ 01 BE	Clean

Bulk Tank Status @ 2400				
01	0	Bentonita	-	Clean
02	0	Bentonita	-	Clean
03	0	Cement	BLD LW 7.5	Clean

Master: Max Barreiros

04	0	Baritina	-	Clean	