

1. Incident Name: Rupture of HOSE during offloading operation

2. Operational Period (Date / Time): October 30th
From: 8:00 To: 15:00

3. Check-In Location: Command Post Other Staging Area

CHECK-IN LIST (Personnel) ICS 211p-OS

Personnel Check-in Information				8. Initial Incident Check-In?	9. Time	
4. Name	5. Company / Agency	6. ICS Section / Assignment / Quale.	7. Contact Information	(X)	In	Out
Ronaldo Palmeira	Tetrattech			<input type="checkbox"/>	8:00	14:34
Pedro Martins	O'Brien	OPS	21-981382588	<input checked="" type="checkbox"/>	8:00	14:45
MARCOS DA COSTA	CVX	TI		<input type="checkbox"/>	8:00	15:00
Ricardo VIEIRA	CVX	TI		<input type="checkbox"/>	8:00	14:38
LUCIANO TERRIGNO	CVX	TI	21-98121-4244	<input type="checkbox"/>	8:10	14:38
RODRIGO MARTINS	CVX	TI	21-981126455	<input type="checkbox"/>	8:20	15:00
Pedro Pinto	CVX	TI	21-98128-2806	<input type="checkbox"/>	7:20	14:45
MARCIO R. Rangel	CVX	HUT	21-981124918	<input type="checkbox"/>	7:20	15:00
Luiz Mendonça	CVX	HOS	21-98157-3644	<input type="checkbox"/>	8:21	14:40
EDUARDO ACETE	CVX	OPS	21-97698-8884	<input type="checkbox"/>	8:25	14:30
Isabela Behen	CVX	PLANNING EUL	21 98217-5212	<input type="checkbox"/>	8:25	15:00
RASSI	CVX	OPS	998159 3300	<input type="checkbox"/>	8:26	14:30
Caio Faini	CVX	OPS	21 98219-1485	<input type="checkbox"/>	8:27	14:30
Murilo Machado	CVX	PGPA	21 98318 0860	<input type="checkbox"/>	8:27	14:50
Marilena Brummel		PGPA	21 99939 0325	<input type="checkbox"/>	8:28	14:30
Luiza Arruda	CVX	BD	21 982131113	<input type="checkbox"/>	8:29	14:45
BRUNO GUEDES	CVX	IC	21 98187 0392	<input type="checkbox"/>	8:30	14:50
RACHEL PINTO	CVX	PSC	21 98217 3092	<input type="checkbox"/>	8:30	15:00
HUGO MORENO	HIDROCUEN	OPS	21 99331 6606	<input type="checkbox"/>	8:30	14:29
BRAD WENDT	CVX	Repty IC	21 98218 3222	<input type="checkbox"/>	8:31	21:50
EVANILDE OLIVEIRA	CVX	HES	21 98218 6757	<input type="checkbox"/>	8:31	15:00

10. Prepared by: _____ Date / Time: _____

11. Date / Time Sent to Resources Unit: _____

Electronic version NOAA 1.0 June 1, 2000

offloading operations

1. Incident Name	2. Operational Period (Date / Time)	3. Check-in Location		CHECK-IN LIST (Personnel) ICS 211p-OS			
Rupture of hose during offloading operations	October 30th From: 8:00 To: 15:00	<input type="checkbox"/> Command Post	<input type="checkbox"/> Other				
Personnel Check-in Information				8. Initial Incident Check-In?		9. Time	
4. Name	5. Company / Agency	6. ICS Section / Assignment / Quals.	7. Contact Information	(X)	In	Out	
PABLO BONILLA	CVX	PLANNING CHIEF	981593838	<input type="checkbox"/>	08:54	09:21	
SERGIO BICACHO	CVX	LOGISTICS	98312-2948	<input type="checkbox"/>	08:35	14:30	
MARCELO ANAP	CVX	PLANNING	98181-1377	<input type="checkbox"/>	08:35	15:00	
PABLO ROMERO	CVX	LOGISTICS	98157-5152	<input type="checkbox"/>	08:36	14:31	
SERGIO PARRAS	CVX	NO SV	98893 3237	<input type="checkbox"/>	8:38	14:30	
ANA LYRA	O'BRIEN'S	Planning	96969-3338	<input type="checkbox"/>	8:42	14:44	
ANDRE CRYE	CVX	FINANCE	99628-0701	<input type="checkbox"/>	8:49	14:30	
PAULA PEDRAS	CVX	RH	99958 1713	<input type="checkbox"/>	8:50	14:15	
LUIZ AWES	CVX	Supply	98306 4131	<input type="checkbox"/>	8:50	9:15	
Mario Junior	CVX	SCM	99866156	<input type="checkbox"/>	8:50	14:30	
Monica Skowronski	CVX	Legal	98112 7364	<input type="checkbox"/>	8:54	12PM	
Patricia Matson	CVX	SITUATION UNIT	981575231	<input type="checkbox"/>	8:58	10:26	
PABLO BONILLA	CVX	PSC	981593838	<input type="checkbox"/>	9:27	14:34	
BEN SLOAN	CVX	VISITOR	981052263	<input type="checkbox"/>	9:32	4:50	
Jannice	CVX	Situation	98112-5865	<input type="checkbox"/>	11:00	15:00	
ALAN BRUNSON	CVX	LOGISTICS	98217-4024	<input type="checkbox"/>	11:35	11:45	
Paulo Solorzano	CVX	LEGAL	98283-3783	<input type="checkbox"/>	11:42	14:30	
PATRICIA PRADA	CVX	BD REGN	98112-7087	<input type="checkbox"/>	12:10	12:45	
STELLA GOMES	CVX	ENV-SUPERVISOR	98157-3720	<input type="checkbox"/>	13:40	14:46	
Vanessa Fernandes	CVX	FINANCE	99384-2984	<input type="checkbox"/>	13:40	14:25	
CEZAR TABA	CVX	Assett Advisor	98199-3946	<input type="checkbox"/>	14:10	14:31	
10. Prepared by:			Date / Time		11. Date / Time Sent to Resources Unit		

Electronic version NOAA 1-0 June 1, 2000

1. Incident Name *Rupture of hose during offloading operation*

2. Operational Period (Date / Time)
 October 30th
 From: *8:00* To: *15:00*

3. Check-in Location
 Command Post Other
 Staging Area

CHECK-IN LIST (Personnel)
 ICS 211p-OS

Personnel Check-in Information				8. Initial Incident Check-In?	9. Time	
4. Name	5. Company / Agency	6. ICS Section / Assignment / Quals.	7. Contact Information	(X)	In	Out
<i>Antonio Suarez</i>	<i>LVX</i>	<i>IT</i>	<i>989 05-1934</i>	<input type="checkbox"/>	<i>8:00</i>	<i>15:00</i>
				<input type="checkbox"/>		
				<input type="checkbox"/>		
				<input type="checkbox"/>		
				<input type="checkbox"/>		
				<input type="checkbox"/>		
				<input type="checkbox"/>		
				<input type="checkbox"/>		
				<input type="checkbox"/>		
				<input type="checkbox"/>		
				<input type="checkbox"/>		
				<input type="checkbox"/>		
				<input type="checkbox"/>		
				<input type="checkbox"/>		
				<input type="checkbox"/>		
				<input type="checkbox"/>		
				<input type="checkbox"/>		
				<input type="checkbox"/>		
				<input type="checkbox"/>		
				<input type="checkbox"/>		
				<input type="checkbox"/>		
				<input type="checkbox"/>		
				<input type="checkbox"/>		
				<input type="checkbox"/>		
				<input type="checkbox"/>		
				<input type="checkbox"/>		
				<input type="checkbox"/>		
				<input type="checkbox"/>		

10. Prepared by: _____ Date / Time _____

11. Date / Time Sent to Resources Unit _____

