

CHEVRON BRASIL PETRÓLEO LTDA - VESSEL DAILY MIDNIGHT REPORT

Vessel Name:	OSRV MAGÉ		
Report Number:	397	Block:	FRADE
Date:	7-mai-15		

From	То	Operations					
0001	0600	At 00:01 - 06:00 hours - MV Mage - Standby to FPSO Frade.					
0601	1200	At 07:50 hours - MV Mage - Standby boat during Helicopter operations on FPSO Frade . At 08:05 hours - MV Mage - Helicopter departure. At 08:00 - 08:30 hours - MV Mage - Daily Security Dialogue - Task accomplished. At 09:30 hours - MV Mage - Connected Miros Radar. At 10:40 hours - MV Mage - Standby boat during Helicopter operations on FPSO Frade . At 10:50 hours - MV Mage - Helicopter departure. At 10:51 - 12:00 hours - MV Mage - Standby to FPSO Frade.					
1201	1800	At 12:50 - 14:35 hours - MV Mage - Oil Spill Drill. At 15:20 hours - MV Mage - Disconnected Miros radar . Nothing was found regarding oil stain . At 15:21 - 18:00 hours - MV Mage - Standby to FPSO Frade.					
1801	2359	At 18:01 - 23:59 hours - MV Mage - Standby to FPSO Frade.					

Stock Levels on Board							
Product	Start	Load	Discharge	Use	End	Remarks	
Fuel (m ³)	107,55	0,00	0,00	3,74	103,81	Standby waiting for Chevron instructions	
Pot Water (m ³)	327,80	0,00	0,00	3,50	324,30		
Drill Water (m³)	0,00	0	0	0	0,00		
SLOP Mud (bbls)	0,00	0	0	0	0,00		

Remarks: Next crew change : May 14th,2015.

Port Liq Mud Tank Status			STB	STBD Liq Mud Tank Status			BULK Tank Status		
#1	0		#1	0			#1	0	
#2	0		#2	0			#2	0	
#3	0		#3	0			#3	0	
#4	0		#4	0			#4	0	
Vessel Cre	ew:	13	Safety	Mtgs:	2				
Passenge	rs:	1	Pre Jobs :		2	1			
JSA Chec	klists:	0	Safe V	WISE cards: 0		Dinto	Dinto		
Near Miss	Near Misses: 0		Unsaf	Unsafe WISE Cards : 0		Master:		Pinto	
Permit to Work: 0		Rigge	Rigger Cards: 0						
Safety Dril	Safety Drills: 0								