



Detalhes da Mensagem



Nome do Veículo	FISSURADO		
Número do Veículo	948955		
Mensagem	MACRO_16	Data de Criação	17/03/2015 01:06:00
GMN	187417811	Data do Recebimento	17/03/2015 01:06:06
Status	Não Lida	Data da Leitura	
Prioridade	Normal	Data da Posição	17/03/2015 01:04:51
Latitude	21° 54' 12" Sul	Longitude	39° 51' 55" Oeste
Posição	0,24 mi NO De FPSO FRADE, - Brasil		



Detalhes da Mensagem



RELATORIO DIARIO (DAILY REPORT)

1)INFORMACOES GERAIS (GEN. INFORM.):

EMBARCACAO (LHV): TS FISSURADO
COMTE.(CAPTAIN): HELIO JOAO DA SILVA
DATA DO RELAT.(REPORT DATE): 16/03/15
LOCACAO(LOCATION): BACIA DE CAMPOS
TRIPULANTES A BORDO(CREW ON BOARD): 08
TRIPULANTES EM TREINAMENTO(SSE): 00
HOMEM-HORA TRIP.(CREW WKMAN-HOUR): 96
ESTOQUE O. DIESEL(DO ROB): 53600LTRS
CONS. DIARIO O.DIESEL 550LTRS
ESTOQUE AGUA DOCE(FW ROB): 77000 LTRS
CONS. DIARIO AGUA DOCE:2000LTRS
ESTOQUE DISPERS.(DISP. ROB): 2000 LTRS

2)INF. DE SEGURANCA(SAFETY INFORM.):

ATOS INSEGUROS(UNSAFE ACTS): 00
COND. INSEGURAS(UNSAFE COND.): 01
OBS. TRAB. SEGUROS(SAFE WORK OBS.): 00
PARADA DE TRABALHO(STOP WORK): 00
CARTOES DE OBS.(BBS CARDS): 01
PERMISSOES DE TRABALHO(PTW): 00
PRE-TAREFAS(PRE-JOBS): 01
EXERCICIOS SEG.(SAFETY DRILLS): 01
INCID. PESSOAIS(PERS. INCID.): 00
INCID. AMBIENTAIS(ENV. INCID.): 00
INCID. MATERIAIS(MAT. INCID.): 00

3)TAREFAS REALIZADAS(PERFORMED TASKS):

00:00 HS AS 06:20 STBY P/ FPSO FRADE
06:20 HS AS 06:50 INSPE@AO MANGOTE
06:50 HS AS 09:20 STBY P/ FPSO FRADE
09:20 HS AS 10:35 EXERCICCIO DE LAN@A
MENTO DE BARREIRAS
10:35 HS AS 24:00 STBY P/ FPSO FRADE

4)OUTRAS INFORMACOES(OTHER INFORM.):

PLANILHA INSPE@AO MANGOTE N.074
A=OK,B=OK,C= TODAS OPERACIONAIS,D=OK,
E=OK,F=OK,G= NAO INSTALADA.

Observação



Detalhes da Mensagem

