Vessel	L	AHTS Re	edbur	ck					0103	13 FFI	3 2015			
Vessel AHTS Reedbuck Report No. CHEVRON DR 20150213						-	Block	13111	5 2015					
Report	NU.		CITEV	NON_DR_201.	50215				DIOCK					
Guana	abara Bay	0000		Suanabara Bay	1105	. Δ	tanchor	in Guan	abara Bay a	area #064				
Jualla	ubara bay	0000		Juanavara Ddy	1100		e unenor	Guan	asara bay c					
Guana	abara Bay	1105	6	Guanabara Bay	1125	s v	Vessel on DP. Start oil spill exercise with the crew and hidroclean team.							
Guana	abara bay	1105		Juanabara bay	1125		esser on Dr. start on spin exercise with the trew and muroclean (eam.							
Guana	abara Bay	1125	6	Guanabara Bay	1250) F)	Eversise stepped by lunchtime							
Guanabara Bay 1125				Judildudid Ddy	1250		Exercise stopped by lunchtime.							
Cuenc	ahara Davi	1250			1415	: р	octart oi		rcico					
Guanabara Bay 1250			Guanabara Bay	141.		Restart oil spill exercise.								
Cuenc	ahara Davi	1415			1535		nich ovo	rcico To	king back o	il cnill hoor	~			
Guana	abara Bay	1413		Guanabara Bay	1333	E1		illise. Ta	KING DACK O					
<u></u>	- have Davi	1525		Succession Devi	2105			off Ato	nchar in ar	aa #0C				
Guanabara Ba		y 1535 G		Guanabara Bay	2105	v	Vessel DP off. At anchor in area #06.							
<u></u>	- have Davi	2105		Due e e e De ut	2210		transit	to Dracas	Deek					
Guana	abara Bay	2105		Brasco Port	2210) IN	i transit	to Brasco	о роск.					
	. .	2240		<u> </u>	2227									
Bras	sco Port	2210)	Brasco Port	2335		loored a	it brasco	dock makir	ng cargo op	erations.			
Bras	sco Port	2335	Ģ	Guanabara Bay	2355	5 0	nmoore	d from b	rasco dock.	Vessel in t	ransit to a	nchor area.		
				_			<u> </u>							
Guana	abara Bay	2355	0	Guanabara Bay	2400) At	t anchor	in Guan	abara Bay a	area #06.				
												_		
	Product	t		0001	Receiv	/e	Disch	narge	Used	Corr +/-	2400	Rema	irks	
Diesel N	И³			656.27		-		-	5.7	-	650.57	Available		
												for Rig		
Potable	e Water M ³			304.0		-		-	8.0	-	296.0	Available		
												for Rig		
Drill Wa	ater M ³			507.6		-		-	-	-	507.6	Available		
												for Rig		
Cement MT			0		-		-	-	-	0				
Barite MT Bentonite MT			0		-		-	-	-	0				
				0		-		-	-	-	0			
SBM Mud BBL			0				-	-	-	-				
Base Oil BBL			0				-	-	-	-				
WBM Mud BBL Brine BBL			0	0			-	-	-	0				
DI III E B	DL			U		-	1	-	-	-	0			
CDN/ 14	Enna		DDI				T	Г		I	0			
SBM 11				0		-		-	-	-	0			
Saraline SLOP - I	e 6.4ppg			0		-		-	-	-	0			
				0		-		-	-	-	0			
SBM 10			BBL	0		-		-	-	-	0%			
Deck IN	Use (%)			U		-	1	-	-	-	0 %		I	
			afoty	/ Personnel Da	ita					Detai	ls on Safat	y Reports or	Drille	
	Cre			Rigger CD	1	NL	ear Miss	0		Deidi				
						INC								
Passeng				Safety drill	0		Pre Job			Crew Change 24/Fev/2015				
		EA 9		Safety Meets	0	<u> </u>	PTW				Ŭ			
	Safe WI	SE 0		Unsafe WISE	0	Sto	op Work	0						
			<u>.</u>	Taul Class Ca	2400		1	1	0 7 55					
			PORT Liquid Mud Tar									Tank Status @ 2400 ear Recovery Clean		
			1						1.1.661		Clear R	OCOVORY	Clean	
52	51 bbl	Clean			overy		Clean	52	51 bbl					
53	51 bbl 0	Clean Clean			MT	C	Clean	53	0	(Clear	MT	Clean	
53 54	51 bbl 0 0	Clean Clean Clean			MT MT	C	Clean Clean	53 54	0 0	(Clear Clear	MT MT	Clean Clean	
53	51 bbl 0	Clean Clean			MT	((Clean	53	0	(C Bas	Clear	MT	Clean	

		Bulk Tank	Status @ 2400	Master: Fonseca	
55	0	Clean	-	Clean	
56	0	Clean	-	Clean	
57	0	Clean	-	Clean	
58	0	Clean	-	Clean	