

Vessel: Campos Carrier

Block: Frade

Report No: CCarrier_DR_20091006

Date: terça-feira, 6 de outubro de 2009

From	To	Operation
00:00	13:00	Stby to Sedco 706 W.O.O
13:00	14:15	Oil Spill Drill with TS Fissurad, Skimer and Ro Boom on the water.
14:15	15:20	Stby to Sedco 706 W.O.O
15:20	24:00	A/S Sedco 706, transfer deck cargo

STOCK LEVELS ON BOARD

Product	Start	Load	Discharge	Used	End	Corr	Remarks
Diesel M ³	752,5			15,0	737,5		Available for Rig 378
Potable Water M ³	77			5	72		
Drill Water M ³	0				0		Available for Rig 0
Cement MT	98				98		
Barite MT	100				100		
Bentonite MT	0				0		
SBM Mud BBL	0				0		
Base Oil BBL	0				0		
WBM Mud BBL	0				0		
Brine BBL	0				0		
SBF Mud (bbl)							
Calc Carb (mT)							
Flo-Pro (bbl)							
SLOP Tk (bbl)	600				600		
Deck in Use (%)	84	15	4		95		

Remarks: W Safe: C/O Julio 1 / 2Mate Patricia 1 / 1Eng Joao 1 / 2Eng Batista 1
Oiler Rasseli 1 / GH Evandro 1

1	Brine residue
2	Brine residue
3	600 bbl SLOP
4	Clean

1	Brine residue
2	Brine residue
3	SBM residue
4	Clean

1	Cement Blended	48 ton
2	Cement Batch 384	50 ton
3	Barite	100 ton
4	Calcium Carb residue	
5	Clean	

Vessel Crew:	15
Passengers:	0
JSA Checklists:	3
Near Misses:	0
Permit to Wrk:	2
Safety Drills:	1

Safety Mtgs:	0
PreJobs:	17
Safe WISE Cards:	6
Unsafe WISE Cards:	0
Rigger Cards:	2

Antonio Nogueira
Master