

Date: 11/25/2009 Campos Contender Report No: CContender_DR_20091125

00:00 24:00 Heading management with FPSO Frade

Product	Start	Load	Dsch	Used	End	
Diesel	575,3	0	18.6		556,7	Avail for Rig: 307
Pot Water	65	30	0	7	88	
Drill Water	300	0	0		300	Avail for Rig: 0
Cement	0	0	0		0	
Barite	0	0	0		0	
Bentonite	0	0	0		0	
SBM Mud	0	0	0		0	
Base Oil	276	0	0		276	bbl
WBM Mud	0	0	0		0	
Brine	0	0	0		0	
Ethanol(m ³)	0	0	0		0	
Fwater	350	0	30		320	
Total water	1274	0	7		1267	
Deck Used (%)	0	0	0		0	

Port Liq Mud Tanks

#1 residue mud sbm
#2 dirty
#3 Empty
#4 empty
#5 empty

Stbd Liq Mud Tanks

#1 residue mud sbm
#2 dirty
#3 dirty
#4 empty
#5 276 bbl

Bulk Tanks

#1 empty
#2 empty
#3 empty
#4 empty

Crew: 14 Pass: 0 Capt: Marcos Aurélio Costa da Silva
Rigger: 0 Near Miss: 0 PreJob: 4 PTW: 1 Sfty Mtg: 1 Drills: 0
WISE Safe: 0 WISE Unsafe: 2 JSA: 0

06:50LT- Heading 205,Power40%; 11:55LT- Heading 210, Power40%; 22:20LT- Heading 180, Power 55%; At 17:00LT, oil spill drill using disperse equipments; Crew change at Dec 1st, 2009.