

Vessel: Campos Carrier

Block: Frade

Report No: CCarrier_DR_20090910

Date: quinta-feira, 10 de setembro de 2009

From	To	Operation
00:00	02:00	a/s S706 finished brine transfer
02:00	07:10	stdby S706 for operations
07:10	09:00	a/s S706 MDO transfer
09:00	12:35	stdby S706 for MDO transfer
12:35	13:40	Oil Spill Exercise
13:40	16:00	a/s S706 MDO transfer
16:00	24:00	underway to Brasco

STOCK LEVELS ON BOARD

Product	Start	Load	Discharge	Used	End	Corr	Remarks
Diesel M ³	1.047,2		246,0	19,3	781,9		Available for Rig 422
Potable Water M ³	95			5	90		
Drill Water M ³	0				0		Available for Rig 0
Cement MT	98				98		
Barite MT	100				100		
Bentonite MT	0				0		
SBM Mud BBL	0				0		
Base Oil BBL	0				0		
WBM Mud BBL	0				0		
Brine BBL	2138		2138		0		
SBF (bbl)							
Calcium(bbl)	35				35		
SLOP Tk (bbl)							
Deck in Use (%)	68	10	5		73		

Remarks: w.safe: eng batista:01 / ab joel: 01
Oil Spill Exercise

PORT Liq Mud Tank Status	
1	brine residue
2	brine residue
3	mud residue
4	SBM residue/9 .4 ppg

STBD Liq Mud Tank Status	
1	brine residue
2	brine residue
3	mud residue
4	SBFresidue / 6.4 ppg

BULK Tank Status	
1	Cement Blended 48 ton
2	Cement Batch 3845 0 ton
3	Barite 100 ton
4	Calcium Carb 35 ton
5	Clean

Vessel Crew:	14
Passengers:	0
JSA Checklists:	0
Near Misses:	0
Permit to Wrk:	0
Safety Drills:	0

Safety Mtgs:	0
PreJobs:	10
Safe WISE Cards:	2
Unsafe WISE Cards:	0
Rigger Cards:	3

Walker Calvet
Master