Vessel:	Campos Carrier	Block:	Frade
Report No:	CCarrier_DR_20090714	Date:	terça-feira, 14 de julho de 2009

From	To	Operation
00:00	09:00	standby S706 for operations
09:00	13:20	IBAMA / skimmer drill close S706
13:20	24:00	standby S706 for operations

STOCK LEVELS ON BOARD

Product	Start	Load	Discharge	Used	End	Corr	Remarks
Diesel M^3	981,3			13,6	967,7		*Available for Rig* 608
Potable Water M^3	85			5	80		
Drill Water M^3	0				0		*Available for Rig* 0
Cement MT	138				138		
Barite MT	60				60		
Bentonite MT	0				0		
SBM Mud BBL	1549				1549		
Base Oil BBL	0				0		
WBM Mud BBL	0				0		
Brine BBL	0				0		
SBF (bbl)	675				675		
SLOP Tk (bbl)							
Deck in Use (%)	30				30		

Remarks: w.safe: ab lucio:01

PORT Liq Mud Tank Status	
1	Clean
2	Clean
3	SBM 420 bbl / 9.4 ppg
4	SBM residue / 9.4 ppg

STBD Liq Mud Tank Status	
1	Clean
2	Clean
3	SBM 1129 bbl / 9.4 ppg
4	SBF 675bbl 6.4 ppg

BULK Tank Status	
1	Cement Blended 48 ton
2	Cement 90 ton
3	Barite 60 ton
4	Clean
5	Clean

Vessel Crew:	14
Passengers:	0
JSA Checklists:	0
Near Misses:	0
Permit to Wrk:	0
Safety Drills:	1

Safety Mtgs:	0
PreJobs:	5
Safe WISE Cards:	1
Unsafe WISE Cards:	0
Rigger Cards:	0

Walker Calvet
Master