Vessel:	Campos Carrier	Block:	Frade
Report No:	CCarrier_DR_20091128	Date:	sabado, 28 de novembro de 2009

From	To	Operation
00:00	11:00	Stby Sedco 706 for operations due weather conditions
11:00	12:25	Oil Spill Exercise
12:25	24:00	Underway to Rio Pilot

STOCK LEVELS ON BOARD

Product	Start	Load	Discharge	Used	End	Corr	Remarks
Diesel M^3	897,9			10,0	887,9		*Available for Rig 528*
Potable Water M^3	435			5	430		
Drill Water M^3	247				247		*Available for Rig 247*
Cement MT	0				0		
Barite MT	50				50		visual estimated amount
Bentonite MT	0				0		
SBM Mud BBL	0				0		
Base Oil BBL	0				0		
WBM Mud BBL	0				0		
Brine BBL	0				0		
SBF Mud (bbl)							
Calc Carb (mT)							
Flo-Pro (bbl)							
SLOP Tk (bbl)	70				70		
Deck in Use (%)	30		3		27		

Remarks: w.safe: Oiler-Rasseli 01 / G/H-Evandro 02 / 2nd Eng-Fabio 01 / 1st Eng-Joao 01
Oil Spill drill

PORT Liq Mud Tank Status	
1	clean
2	drill water 100cbm
3	cleaning stopped
4	SBM residue 7.5 ppg

STBD Liq Mud Tank Status	
1	clean
2	drill water 147cbm
3	clean
4	SBF residue 6.4 ppg

BULK Tank Status	
1	Cement residue
2	Cement Batch 384 residue
3	Barite 50 ton
4	Calcium Carb residue
5	Clean

Vessel Crew:	14
Passengers:	0
JSA Checklists:	2
Near Misses:	0
Permit to Wrk:	1
Safety Drills:	2

Safety Mtgs:	0
PreJobs:	12
Safe WISE Cards:	5
Unsafe WISE Cards:	0
Rigger Cards:	1

Antonio Nogueira
Master