

Vessel: Campos Carrier

Block: Frade

Report No: CCarrier\_DR\_20100123

Date: sábado, 23 de janeiro de 2010

From	To	Operation
00:00	02:15	Stby Sedco 706 for operations
02:15	07:00	A/S Sedco 706, cargo transfer
07:00	24:00	Stby Sedco 706 for operations

**STOCK LEVELS ON BOARD**

Product	Start	Load	Discharge	Used	End	Corr	Remarks
Diesel M <sup>3</sup>	695,9			17,0	678,9		<i>Available for Rig 319</i>
Potable Water M <sup>3</sup>	104			5	99		
Drill Water M <sup>3</sup>	907				907		<i>Available for Rig 907</i>
Cement MT	0				0		
Barite MT	51				51		
Bentonite MT	0				0		
SBM Mud BBL	0				0		
Base Oil BBL	326				326		
WBM Mud BBL	0				0		
Brine BBL	0				0		
SBF Mud (bbl)							
Calc Carb (mT)							
Flo-Pro (bbl)							
SLOP Tk (bbl)	10				10		
Deck in Use (%)	30	20	30		20		

Remarks: -w.safe: 2nd mate-Patricia 01 / 2nd Eng-Fabio 01 / Oiler-Rasseli 01 / O/S-Tiago 01 / AB-Ednaldo 01.  
 -Spill Oil drill with Skimmer.

PORT Liq Mud Tank Status	
1	Drill water 300 cbm
2	Drill water 155cbm
3	slop residue
4	Clean

STBD Liq Mud Tank Status	
1	Drill water 300 cbm
2	Drill water 152cbm
3	Clean
4	BioBase 360-SBF 326 bbl

BULK Tank Status	
1	Clean
2	Cement batch 394 residue
3	Barite 51 tons
4	Clean
5	Clean

Vessel Crew:	14
Passengers:	0
JSA Checklists:	2
Near Misses:	0
Permit to Wrk:	1
Safety Drills:	1

Safety Mtgs:	1
PreJobs:	12
Safe WISE Cards:	5
Unsafe WISE Cards:	0
Rigger Cards:	2

Antonio Nogueira  
Master