Report No:   CContender_DR_20100523							Da	Date: domingo, 23 de maio de 2010				
From	То					Ор	eration					
00:00	24:00	Pul	Back with I	MV Vad	ela							
		_										
		-										
		-										
		_										
	•			9		K LEVEL	S ON B	OAPD.				
Dre	oduct		Start	Load				End	_	Corr	Remarks	
Diesel M		$\dashv$		Load	u	Discharge	+			JOIL		
		3	623,5 109				19,1	604,4 102			Available for Rig 354	
Potable Water M <sup>3</sup> Drill Water M <sup>3</sup>		+	220				+ '	220			Available for Rig 220	
Cement		$\dashv$	0				1	0			Thumasis is in a second	
Barite MT			0				1	0				
Bentonite MT			0				]	0				
SBM Mud BBL			0					0				
Base Oil BBL		0				1	0					
WBM Mud BBL		0				4	0			bbl		
Brine BBL		0				_	0					
Ethanol(m³) 89					4	89			m³ m³			
Fwater452Total water1534					1	452 1534			m³			
TOtal We	ate:	$\dashv$	1004				†	1334			<u>                                     </u>	
							1					
Deck in Use (%) 0					i i	0			<u> </u>			
Remarks: 09:00h - OIL SPILL DRILL v			ith a	II crow moi	mhars							
Komark								OIL SPILL D	RIL	.L.		
PORT Liq Mud Tank Status						STBD Liq Mud Tank Status					BULK Tank Status	
1 CLEAN				1	Dirty ( Slop) 3m <sup>3</sup>				1	Cleaned		
2 CLEAN				2	CLEAN				2	Empty		
ET 89 m <sup>3</sup>				3	CLEAN				3	dirty cement		
B1 DIRTY				DIRTY				4	Dirty cement			

Block: Frade

Vessel Crew:	14
Passengers:	0
JSA Checklists:	3
Near Misses:	0
Permit to Wrk:	2
Safety Drills:	1

B2 DIRTY

Vessel: Campos Contender

Safety Mtgs:	1
PreJobs:	8
Safe WISE Cards:	6
Unsafe WISE Cards:	3
Rigger Cards:	0

BO Clean

Lucas de Santa Rosa

Master