Vessel	AHTS CAMPOS CONTENDER		0007	September, 09th 2013
Report No.	CHEVRON_ DR_ 20130909		Block	

RIO DE JANEIRO	0000	RIO DE JANEIRO	0950	ANCHORED IN GUANABARA BAY
RIO DE JANEIRO	0950	RIO DE JANEIRO	1820	VESSEL IN MODE DP GUAMABARA BAY - DRILL OIL RECOVER
RIO DE JANEIRO	1820	FRADE FIELD	2400	UNDERWAY TO FPSO FRADE

Product	0001	Receive	Discharge	Used	Corr	2400	Remarks	
Diesel M³	427,7	450,0	-	4,6	-	873,1	*Available for Rig*	623,1
Potable Water M³	631,0	-	-	6,0	-	625,0	*Avalable for Rig*	485,0
Drill Water M³	546,0	-	-	-	-	546,0	*Avalaible for Rig*	346,0
Cement MT	0	-	-	-	-	0		
Barite MT	0	-	-	-	-	0		
Bentonite MT	0	-	-	-	-	0		
SBM Mud BBL	-	-	-	-	-	-		
Base Oil BBL	-	-	-	-	-	-		
WBM Mud BBL	0	-	-	-	-	0		
Brine BBL	0	-	-	-	-	0		

SBM 11.5ppg	**BBL**	0	-	-	-	-	0		
Saraline 6.4ppg	**BBL**	0	-	-	-	-	0		
SLOP	**BBL**	0	-	-	-	-	0		
SBM 10.4ppg	**BBL**	0	-	-	-	-	0		
Deck in Use (%)		45	-	-	-	-	45		

Safety / Personnel Data					
Crew	15	Rigger CD	-	Near Miss	-
Passengers	05	Safety drill	01	Pre Job	20
JSA	04	Safety Mtg	-	PTW	04
Safe WISE	-	Unsafe WISE	-	Stop Work	-

Details on Safety Reports or Drills

Drill: Oil Recover

PORT Liq Mud Tank status @ 2400				
01	0	Clean	Pad Mud	Clean
02	0	Clean	Pad Mud	Clean
03ET	0 m3	Other	Etanol (BBLS)	Used
074B1	000	Brine	TQ 01 BB	Clean
5B1	000	Brine	TQ 02 BB	Clean

STBD Liq Mud Tank staus @ 2400				
01	0	Clear	Pad Mud	Clean
02	0	Clear	Pad Mud	Clean
03	0	Other	Slop	Clean
4B1	000	Base Oil	TQ 01 BE	Clean
5BO	000	Base Oil	TQ 01 BE	Clean

Bulk Tank Status @ 2400				
01	0	Bentonita	-	Clean
02	0	Bentonita	-	Clean
03	0	Cement	BLD LW 7.5	Clean
04	0	Baritina	-	Clean

Master: RODRIGO MERGULHÃO.