

Vessel: Campos Carrier

Block: Frade

Report No: CCarrier_DR_20100907

Date: terca-feira, 7 de setembro de 2010

From	To	Operation
00:00	00:50	Stby Sedco 706 for operations
00:50	01:00	Entry Sedco 706 500m zone, Approaching DP
01:00	02:30	A/S Sedco 706, Slop transfer
02:30	14:20	stby Sedco 706 for operations
14:20	14:35	Entry Sedco 706 500m zone, approaching DP
14:35	17:15	Boom Deployment and Skimmer Drill
17:15	24:00	Stby Sedco 706 for operations

STOCK LEVELS ON BOARD

Product	Start	Load	Discharge	Used	End	Corr	Remarks
Diesel M ³	895,2			9,0	886,2		Available for Rig 526
Potable Water M ³	83			5	78		
Drill Water M ³	0				0		Available for Rig 0
Cement MT	0				0		
Barite MT	100				100		
Bentonite MT	45				45		
SBM Mud BBL	0				0		
Base Oil BBL	0				0		
WBM Mud BBL	0				0		
Brine BBL	6200		1000		5200		
SBF Mud (bbl)							
Calc Carb (mT)							
Flo-Pro (bbl)	2300				2300		
Gel - PHB (bbl)							
SLOP Tk (bbl)	90	60			150		
Deck in Use (%)	70				70		

Remarks: w.safe: C/O-Julio 02 / AB-Wallace 01 / AB-Ednaldo 01 / GH-Evandro 01 / Petty Officer-Rasseli 01.
w.unsafe: C/O-Julio 01.

PORT Liq Mud Tank Status	
1	Brine 1550 bbl
2	Brine 1050 bbl
3	Slop 150 bbl
4	Flo-pro 1150 bbl

STBD Liq Mud Tank Status	
1	Brine 1550 bbl
2	Brine 1050 bbl
3	Flo-pro residue
4	Flo-pro 1150 bbl

BULK Tank Status	
1	Barite 100 ton
2	clean
3	Calcita residue
4	Bentonite 45 ton
5	Cement Residue

Vessel Crew:	14
Passengers:	0
JSA Checklists:	1
Near Misses:	0
Permit to Wrk:	2
Safety Drills:	1

Safety Mtgs:	1
PreJobs:	17
Safe WISE Cards:	6
Unsafe WISE Cards:	1
Rigger Cards:	2

Antonio Nogueira
Master