

Vessel: Campos Carrier

Block: Frade

Report No: CCarrier_DR_20101020

Date: quarta-feira, 20 de outubro de 2010

From	To	Operation
00:00	09:55	Stby Sedco 706 for operation
09:55	10:20	Entry Sedco 706 500m Zone, approaching DP
10:20	11:00	Stby DP Close Sedco 706, chopper operation
11:00	12:10	A/S Sedco 706, cargo and Pad Mud transfer
12:10	13:10	Oil Spill Drill
13:10	13:30	Entry Sedco 706 500m Zone, approaching DP
13:30	14:10	A/S Sedco 706, for Crew transfer
14:10	15:35	Stby DP 250 mts from Sedco 706 for chopper operation
15:35	15:55	A/S sedco 706 for Crew transfer
15:55	24:00	Stby Sedco 706 for operation

STOCK LEVELS ON BOARD

Product	Start	Load	Discharge	Used	End	Corr	Remarks
Diesel M ³	627,2			10,0	617,2		<i>Available for Rig 257</i>
Potable Water M ³	11			5	6		
Drill Water M ³	0				0		<i>Available for Rig 0</i>
Cement MT	60				60		
Barite MT	100				100		
Bentonite MT	45				45		
SBM Mud BBL	0				0		
Base Oil BBL	0				0		
WBM Mud BBL	0				0		
Brine BBL	0				0		
Pad Mud (bbl)	1834		278		1556		
Calc Carb (mT)							
Flo-Pro (bbl)							
Gel - PHG (bbl)	2454				2454		
SLOP Tk (bbl)	501				501		
Deck in Use (%)	50	5			55		

Remarks: w.safe: C/O-Julio 01 / Petty Officer-Rasseli 01 / Oiler-Jance 02.

PORT Liq Mud Tank Status	
1	Gel PHG Residue
2	Gel PHG 1227 bbl
3	Slop 501 bbl
4	Pad mud 778 bbl

STBD Liq Mud Tank Status	
1	Gel PHG Residue
2	Gel PHG 1227 bbl
3	Clean
4	Pad mud 778 bbl

BULK Tank Status	
1	Barite 100 ton
2	Cement residue
3	Cement 60 ton
4	Bentonite 45 ton
5	Cement residue

Vessel Crew:	14
Passengers:	0
JSA Checklists:	2
Near Misses:	0
Permit to Wrk:	1
Safety Drills:	0

Safety Mtgs:	1
PreJobs:	14
Safe WISE Cards:	4
Unsafe WISE Cards:	0
Rigger Cards:	3

Antonio Nogueira
Master