Vessel:	Campos Carrier	Block:	Frade
Report No:	CCarrier_DR_20101109	Date:	terca-feira, 9 de novembro de 2010

From	To	Operation
00:00	16:25	Underway to Sedco 706
16:25	18:00	OIl Spill Drill - " J" Formation
18:00	19:40	Stby DP from 500m Sedco 706 for operation
19:40	20:25	Approaching DP
20:25	22:15	A/S Sedco 706, Cargo transfer
22:15	24:00	Stby DP 250m from Sedco 706 for operation

STOCK LEVELS ON BOARD

Product	Start	Load	Discharge	Used	End	Corr	Remarks
Diesel M^3	1.002,4			13,0	989,4		*Available for Rig* 629
Potable Water M^3	112			5	107		
Drill Water M^3	0				0		*Available for Rig* 0
Cement MT	60				60		amount correction
Barite MT	100				100		
Bentonite MT	45				45		
SBM Mud BBL	0				0		
Base Oil BBL	1500				1500		SBF Saraline
WBM Mud BBL	0				0		
Brine BBL	0				0		
Pad Mud (bbl)							
Calc Carb (mT)							
Flo-Pro (bbl)							
Gel - PHG (bbl)							
SLOP Tk (bbl)							
Deck in Use (%)	35		5		30		

Remarks: Crewchange schedule 11/Nov/2010.
w.safe: Capt-Nogueira 01

PORT Liq Mud Tank Status	
1	Clean
2	Clean
3	Slop residue
4	Pad mud Residue - 14.2 ppg

STBD Liq Mud Tank Status	
1	Clean
2	Clean
3	SBF 1500 bbl - 6.4 ppg
4	Pad mud Residue - 14.2 ppg

BULK Tank Status	
1	Barite 100 ton
2	Blend cement residue (#405)
3	G Cement 60 ton (# 410)
4	Bentonite 45 ton
5	G Cement residue (#410)

Vessel Crew:	14
Passengers:	2
JSA Checklists:	0
Near Misses:	0
Permit to Wrk:	2
Safety Drills:	0

Safety Mtgs:	1
PreJobs:	11
Safe WISE Cards:	1
Unsafe WISE Cards:	0
Rigger Cards:	1

Antonio Nogueira
Master