

Vessel Name:	PSV Campos Carrier	Block:	Frade
Report Number:	Ccarrier_DR_20101202		
Date:	02 de dezembro de 2010		

From	To	Operation
0000	0025	a/s S706 cement transfer
0025	0150	a/s S706 barite transfer
0150	0405	a/s S706 stby for rig clearing barite hose
0405	0625	a/s S706 barite transfer
0625	0645	a/s S706 awaiting transfer receipt
0645	0830	stby S706 for operations
0830	0900	oil spill drill with FPSO Frade
0900	1420	stby FPSO for oil spill drill
1420	1710	stby S706 for operations
1710	1745	entry S706 500m zone, approaching DP
1745	1850	a/s S706 barite transfer
1850	2400	stby S706 for operations, clearing vessel's dry bulk lines

STOCK LEVELS ON BOARD

Product	Start	Load	Discharge	Used	End	Remarks
Fuel (m ³)	803,9			12,0	791,9	available for rig: 431,9
Pot Water (m ³)	154			5,0	149	
Drill Water (m3)	0				0	
Cement (t)	0				0	
Barite (t)	100		22		78	
Bentonite(t)	45				45	
SBM Mud (bbl)	0				0	
Base Oil (bbl)	0				0	
WBM (bbl)	0				0	
Slop (bbl)	220				220	
SBM (bbl)	0				0	
Deck Cargo (%)	35				35	

Remarks: w.safe: ab lucio:02 / ab evanyr:02

PORT Liq Mud Tank Status		Mud Tank Status		Bulk Tank Status	
#1P	Clean	#1S	Clean	#1	Barite 78ton
#2P	Salt water	#2S	Salt water	#2	Clean
#3P	slop 220bbl	#3S	SBF residue	#3	Residue G cement (#410)
#4P	Clean	#4S	Pad mud residue	#4	Bentonite 45ton
				#5	Residue G cement (#413)

Vessel Crew:	15
Passengers:	2
JSA Checklists	1
Near Misses:	0
Permit to work:	1
Safety drills:	3

Safety Mtgs:	0
Pre jobs:	11
Safe Wise:	4
Unsafe Wise:	0
Rigger cards:	0

Walker Calvet
Master