Vessel: Campos Contender									Block: Frade					
Report No: CContender_DR_20100728									Date: quarta-feira, 28 de julho de 2010					
From To Operation														
00:00	24:00	Stand	by FP	SO Frade	ο _ Δν	vaiting in								
00.00	24.00	Otariu	Бутт	oo i iau	5 - Av	vaiting in	isti ucti	10113						
	+													
	+													
					T 00		ELO							
	oduct		0 1 1			K LEV								
	-	Start	Loa	d	Dischar	ge	Used	End		Corr	Remarks			
Diesel N	M ^o	3	718,7				-+	5,1 4	713,6 106			Available for Rig 464		
Drill Wa	Water M ³	_	857					4	857			Available for Rig 357		
Cement MT			(_					007			Available for Nig 331		
Barite MT			(0					
Bentoni		()					0						
SBM Mud BBL			(0					
Base Oil BBL		_	(_					0			1		
WBM Mud BBL Brine BBL		_	(0			bbl		
Ethanol(m©ø)		+				<u> </u>	_	ľ						
Fwater	+	90 493						90 493			m©ø m©ø			
Total water			154						1544			m©ø		
rotal W	<u> </u>		101	+					1011			mes		
Deck in	Use (%)		(0					
Remark	s:													
	Oil 9	Spill Dr	ill - Dis	spersant	Arm	S								
					_					_				
PORT Liq Mud Tank Status					STBD Liq Mud Tank Status					_		BULK Tank Status		
1 CLEAN				1 CLEAN					4	1	Cleaned			
2 CLEAN ET 90				2 CLEAN 3 Empty					\dashv	3	cleaned Cleaned			
B1 CLEAN			3 Empty B1 CLEAN					\dashv	4	Cleaned				
	EAN				BO Clean					\dashv	-	- CIDALIDA		
۷/۵۹	sel Crew:	14	7 [Safet	y Mtgs:	3	1						
Passengers: 0					PreJobs: 9			7						
JSA C	4	<u> </u>	Safe WISE Cards: 4					Max Barreiros						
Near Misses: 1] [Unsafe WISE Cards: 1 Master										
	nit to Wrk:	4] [R	igger	Cards:	0							
Saf	ety Drills:	1	1											