

Vessel: Campos Contender

Block: Frade

Report No: CContender_DR_20101206

Date: segunda-feira, 6 de dezembro de 2010

From	To	Operation
00:00	08:30	Stand by at Frade Field waiting the shuttle tanker
08:30	09:40	Oil Spill Exercise
09:40	10:00	Connected tug wire; slacking 500m of tug wire
10:00	10:20	Start the tension test
10:20	10:30	Finished the tension's test with maximum of 40 t
10:30	24:00	Pull back of MT Genmar Spyridon, Fpso Frade offload

STOCK LEVELS ON BOARD

Product	Start	Load	Discharge	Used	End	Corr	Remarks
Diesel M ³	736,8			14,8	722,0		Available for Rig 472
Potable Water M ³	48			6	42		
Drill Water M ³	482				482		Available for Rig 0
Cement MT	56				56	tons	
Barite MT	0				0		
Bentonite MT	0				0	bbl	
SBM Mud BBL	0				0	bbl	
Base Oil BBL	0				0		
WBM Mud BBL	0				0	bbl	
Brine BBL	0				0	bbl	
Ethanol(m \emptyset)	73				73	m \emptyset	
Fwater	387				387	m \emptyset	
Total water	1128				1128	m \emptyset	
Deck in Use (%)	0				0		

Remarks: Pull back MT Genmar Spyridon. Not accident/Incident to be reported.1200h-PW:30%-Head:139-Tens:22T/1800h-PW:30%-head-150-Tens:18T/2400h-PW:30%-head:145-Tens:14T

PORT Liq Mud Tank Status	
1	residue SBF
2	residue (mud)
ET	73m \emptyset (ETHANOL)
B1	Clean
B2	Clean

STBD Liq Mud Tank Status	
1	residue SBF
2	Clean
3	Slop residue from 2 STBD
B1	Clean
BO	Clean

BULK Tank Status	
1	Clean
2	Clean
3	Blend Cement 30T (not avail)
4	60 m \emptyset -cement G-0416

Vessel Crew:	14
Passengers:	0
JSA Checklists:	1
Near Misses:	0
Permit to Wrk:	1
Safety Drills:	0

Safety Mtgs:	0
PreJobs:	1
Safe WISE Cards:	1
Unsafe WISE Cards:	0
Rigger Cards:	1

Joao Marcos Hioki
Master