



CPEA
Rua Henrique Monteiro, 90
São Paulo - SP - Brasil
(11) 4082 3200

Slug Test Data Report

Project: Detalhamento de Investigação Ambiental

Number: ID CPEA 685

Client: CDP

Page 1

| | | | |
|---------------------|------------------------|--------------------|----------------|
| Test Well: | PM - 04 | Slug Test: | PM - 04 |
| | | Test Well: | PM - 04 |
| Depth to Static WL: | 1,61 [cm] | Casing radius: | 2,54 [cm] |
| Location: | Porto de São Sebastião | Boring radius: | 5,08 [cm] |
| Recorded by: | Cristian Granzotto | Screen length: | 200 [cm] |
| Date: | 18/12/2008 | Aquifer Thickness: | 600 [cm] |

| | Time [s] | Depth to WL [cm] | Drawdown [cm] |
|----|----------|------------------|---------------|
| 1 | 0 | 1,30 | -0,31 |
| 2 | 60 | 1,37 | -0,24 |
| 3 | 120 | 1,43 | -0,19 |
| 4 | 180 | 1,45 | -0,17 |
| 5 | 240 | 1,45 | -0,16 |
| 6 | 300 | 1,46 | -0,15 |
| 7 | 360 | 1,47 | -0,15 |
| 8 | 420 | 1,47 | -0,14 |
| 9 | 480 | 1,47 | -0,14 |
| 10 | 540 | 1,48 | -0,14 |
| 11 | 600 | 1,48 | -0,13 |
| 12 | 900 | 1,49 | -0,12 |
| 13 | 1200 | 1,50 | -0,11 |
| 14 | 1500 | 1,50 | -0,11 |
| 15 | 1800 | 1,50 | -0,11 |